

Care instructions Pleated Fabrics

The Lienesch pleated fabrics are easy to clean. The pleated fabric can simply be swung in appr. 30°C warm fine detergent lye.

Rinse the fabric well, fault the pleats together and push the water out of the blind. The blind should not drop anymore. The blind has to be hanged moist and has to dry closed. During the drying process the blind has to be opened and closed a several times to avoid that the pleats stick together. Do not iron the blind!

Metalized fabrics are not washable, as well as black-out coated fabrics, burn-out fabrics and insectscreen. These fabrics can be cleaned carefully with a moist cloth. Do not rub!

Beware! Avoid that for motorised and handle operated blinds, the mechanical parts do not make contact with water or fluids.

Please note:

Do not clean the windows with any chemical products, which can make direct or indirect contact with the blind. In case of less ventilation condensation spots can arise.

We do not take any responsibility for fabric damages caused by cleaning material or insect excrements.

Out Pleated fabrics are not meant for outdoor use. Because of this, we cannot give any guarantee on the fabrics when these will be placed in a open or partly glassed roof.

Responsibility:

Above mentioned instructions have been drawn up with the utmost care. Nevertheless Grandhome cannot accept any responsibility for cleaning results.

The logo for Lienesch, featuring the brand name in a stylized, handwritten-style font. The letter 'i' is red, and the rest of the letters are black. A registered trademark symbol (®) is located at the end of the word.