


Clearance under cot side with base in lowest position



REVISIONS		
DD/MM/YY	REMARKS	
1	19/02/16	INITIAL ISSUE
2	.../.../...	...
3	.../.../...	...
4	.../.../...	...
5	.../.../...	...